

## Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



## **WORK ORDER INFORMATION**

Work Order Name: WO/80008KN0761/1
Work Order Type: Weatherization
Audit Name: 80008KN0761-Audit

**CLIENT INFORMATION** 

Client Name:

Address:

Client ID: 80008KN0761

Alt. Client ID: KNOX

<u>AGENCY INFORMATION</u>

Agency: Knoxville/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & License Number:	
Contractor's Signature:	

## COMMENT

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

Home built in 1940

An EPA Certified Firm/Renovator is required.

Client Name:

Client ID: 80008KN0761
Alt. Client ID: KNOX

Work Order (Bld Form)

Work Order Name: WO/80008KN0761/1 Report Run On: 5/8/2010 DOE Weatherization Assistant Version 8.6.0

Page 1 of 13

	Measure 1	Double Pane Replacement Feet)(S2)	(10 Squa	re	Componen	ts			Inspected
C	<b>Comment</b> Re Fie	fer to Appendix A- Standards ld Guide.	for Weath	erizati	on Materials	and So	utheast		
					Estimated	•		Actual	
#	Material / Lab	or Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Double Pane Replacement (10 Square Feet)	Each	1					
		Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
C	Other Detail							,	
	***					. ,,,,,,,,			
			1	Measur	e Sub Total:		] ;	Sub Total:	
	Field Notes:			· · · · · · · · · · · · · · · · · · ·	Year.		_	L	

	Measure 2 Mas	tic the Return Box			Componen	ts		<del></del>	Inspected
C	return b allowed.	white Mastic to be applied m board around edges to ox where it meets return i Refer to Appendix A- Sta ast Field Guide.	i fill in any register w	′ voids ith abi	of return to s and mastic. propriate cau	eal all se Seal fron	t of		
	<b></b>				Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Mate	Mastic the Return Box	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					
0	ther Detail								
L									
	[								
				Measure	Sub Total:		S	ub Total:	
	Field Notes:								

1 Construction Mate Mastic/Insulate Supply Each 9 Boot	Boots to part close
of boot where it meets subfloor to be caulked with appropriate caulk. be insulated on outside of boot to R-6. This is best performed with 2-cell foam. No changes allowed. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.  NOTE:When post audit is performed, all boots must be below 1 pasc none over 3 pascals and not more than 3 boots over 1 pascal but les pascals.Location+Register Type^Initial (Pa) Living RoomSupply25.3 Living RoomSupply25.3 Living RoomSupply21.2 Living RoomSupply24.1 KitchenSupply23.2 Bdrm3Supply22.4 Bath3Supply21.7 Bdrm2Supply3.4 Bath1Supply8.1 HallwaySupply31.1  # Material / Labor Description / Comment Units Qty Unit Cost Total Boot  Labor Each 9  Labor Labor Each 9	Boots to part close
none over 3 pascals and not more than 3 boots over 1 pascal but les pascals.Location+Register Type^Initial (Pa) Living RoomSupply25.3 Living RoomSupply21.2 Living RoomSupply23.8 Dining RoomSupply24.1 KitchenSupply23.2 Bdrm3Supply21.7 Bdrm2Supply31.4 Bath1Supply8.1 HallwaySupply31.1  # Material / Labor Description / Comment Units Qty Unit Cost Total  1 Construction Mate Mastic/Insulate Supply Each 9 Boot  2 Labor Labor Each 9	al with s than 3
# Material / Labor Description / Comment Units Qty Unit Cost Total  1 Construction Mate Mastic/Insulate Supply Boot  2 Labor Labor Each 9	
1 Construction Mate Mastic/Insulate Supply Each 9 Boot  2 Labor Each 9	Actual
Boot  2 Labor Each 9	Qty Unit Cost Total
Latin 9	
Other Detail	
Measure Sub Total:	Sub Total:
Field Notes:	<u> </u>

Report Run On: 5/8/2010

	Measure 4 Se	eal & Repair Duct 20 line	ar ft 14"		Componen	ts			Inspected
C	and s must ! minim taped	Duct must be sized correct hortest route, Must be sect be pulled tight so that innerum of R-6 insulation arour with appropriate tape. No ards for Weatherization M	ured with s r liner is fu nd it. Must changes a	straps Ily stre be atta Ilowec	pe installed water alleviate a ptched out. Wached with zing Refer to Ar	vith straig nt saggir lust have p tie and	ng, and a then		
,,					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Unspecified	Seal & Repair Duct (+)	Linear Foot	20					
2	Labor	labor	Linear Foot	20					
c	ther Detail								
						****			
			1	Measur	e Sub Total:		S	Sub Total:	
	Field Notes:		***		E-10.				

	Measure 5 DW	/H Pipe Insulation	· · · · · · · · · · · · · · · · · · ·	, <u></u>	Componen	ts			Inspected
C	Comment								
					Estimated	ı		Actual	<del> </del>
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
		Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.					<u>L</u>		
2	Labor	DHW Pipe Insulation	Each	1					
2	Other Detail								
L									
									3
			1	Measur	e Sub Total:			Sub Total:	
	Field Notes:	un u		71111				<b>a</b>	

Work Order Name: WO/80008KN0761/1 Report Run On: 5/8/2010

Measure	6	Attic	Ins. R-38				Compone	nts A1		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		Inspected
Commen	accessors silicacce	c spa cess. fit an ulatin cone cess a	s labor cost. Conce showing do Install baffles dovering verge. Seal arounder fire resistar and weather standards. Residual southeast and Southeast counter standards.	epth of insi as needed nt. Seal all nd chimney nt foam. In trip with foa efer to App	ulation. Bu I to prever I holes, ga I with shee I stall R-30 I stall R-30 I sendix A-30	uild inso nt loose ps, and t meta fibergl Contrac	or every 30 ulation dan e fill insulat d penetrati I and high ass batt se	00 square 1 around ion from 10 att 10 temperate 10 temperate 11 using 1	att en lic ture att	ic tering before tic	)	
							Estimate	d	_		Actual	
# Material /		or	Description / C		Units	Qty	Unit Cost	Total		Qty	Unit Cost	Total
1 Insulatio	n		Attic Insulation Fiberglass - R		SqFt	1500						
2 Labor			Attic Insulation Fiberglass - R-		SqFt	1500		,,,				
Other Detail	<u> </u>	1										
		[										
					1	Measure	Sub Total:	,,,,	7	s	ub Total:	77
Field Note	s:									//	L	

Client ID: 80008KN0761 Alt. Client ID: KNOX

Measu	re 7 Flo	or Ins. R-19			Componen	ts F1	mer_		Inspected
Comme	Standa subfloo (e.g. standa	es labor cost. Contractor's installing insulation. Control rds. Insulation is installed above (paper side again aves for blankets). Insulations. Refer to Appendicuteast Field Guide.	ractor to in I to mainta est subfloc etion to ha	nstall u ain per or) inclu ve NO	seal penetr sing Resnet manent cont uding necess	ation in f Grade 1 act with s sary supp	the oorts		
					Estimated	·		Actual	
# Materia	l/Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulati	on	Floor Insulation - Fiberglass Batts - R-19	SqFt	1700					.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
2 Labor		Floor Insulation - Fiberglass Batts - R-19	SqFt	1700					
Other Det	ail								
			i	Measure	Sub Total:		s	ub Total:	
Field No	tes:		VI.	/				L.	

Report Run On: 5/8/2010

- 1	Measure 8 DWH	Tank Insulation			Component	s			Inspected
C	omment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	DHW Tank Insulation	Each	1					
		extend pressure relief pipe as needed							
C	ther Detail								
	1.								
•				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Measure 9 Wai	Insulation			Componen		L 1,00AL LL 3,W/		inspected
Contrac Contrac installin interior up area	es labor cost. Contractor notor must dense pack insultor's responsibility to instag wall insulation. Contractor exterior if needed while around house and clean lix A- Standards for Weatl	llation at 3 all wood o ctor's resp e installing siding off	3.5 pou or Styro onsibili o wall ir fafter n	nds per squ foam plugs ty to repair v sulation. Co neasure con	are foot. in holes wall dam ontracto npleted.	after age r to clea Refer to		
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	1265					. ,.
2 Labor	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	1265					OFFICE A STATE OF THE STATE OF
Other Detail								
							- I I I I I I I I I I I I I I I I I I I	
			Measur	Bub Total:			Sub Total:	
Fleld Notes:							<u>_</u>	

1	weasure 10 Ket	rigerator Rpicmnt			Componen	IS			mspecied
С	approva appropi and set packag must be goes to technic certifica Southe	ore or equivalent (must sual). Deliver and install new riate side. Provide client et the temperature controls ing materials and old refrie removed and reclaimed dump. Must provide writian with technician certification. Refer to Appendix Aast Field Guide. Refer to Must be Energy Star.	v refrigera education of appropria igerator from by a certifuten document eation licer A- Standar	tor and on the ately. Com prefied ted nentatinse nuites for '	d ensure han settings of the contractor to mises. Refriction the confrom the moder and lar weatherizati	idles are one refrige remove a gerant chore refrige certified addition Mater	on the rator all narge erator osal	d	
	Ü	, , , , , , , , , , , , , , , , , , ,			Estimated	•		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Refrigerators	Kenmore - 68172	Each	1	- The second sec				
2	Labor	labor	Each	1					
2	Other Detail	7[		1.	) []r		) [	<del>(                                    </del>	
L									V-2011-10 F035-00-00-00-00-00-00-00-00-00-00-00-00-00
				Measur	e Sub Total:		:	Sub Total: [	
	Field Notes:	CORONAL ALLA						,	

Measure 11 CO I	Vionitor is Needed			Componen	ts			Inspected
<b>Comment</b> Refer to Field Gu	Attachment A- Standard uide.	ds for Wea	atheriza			outheas		
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety		Each	1					
	Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	Labor	Each	1					
Other Detail								
		-	Measur	e Sub Total:		] ;	Sub Total:	
<b>(Wal</b> <b>Comment</b> A Certific	tice Lead Safe Weathe Is) ed Firm /Renovator is re opy of Lead Report and	quired to a	adhere		rules. N			Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	EPA RRP Lead Rules	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measure	Sub Total:			Sub Total:	
FleId Notes:				<u> </u>	<b>,,,</b>	•		

Client Name:

Client ID: 80008KN0761 Alt. Client ID: KNOX Work Order (Bid Form)

Work Order Name: WO/80008KN0761/1 Report Run On: 5/8/2010 DOE Weatherization Assistant

Version 8.6.0 Page 12 of 13

Measure 13 Vapor Barrier Needed (Basement/Crawlspace)(QT)			Y 1500SI	Components 1500SF)					Inspected
С	walls and earth. M	6 mil poly. Must be insta d support piers. Must be ust be secured at all sea ization Materials and So	securely ms. Refe	fasten r to Atta	ed. Must be achment A-	cleated o	down to		
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Basement /Crawlspace Vapor Barrier	SqFt	1500		A Company of the Comp			
2	Labor	Labor	SqFt	1500		~~~			
_	Other Detall								
L					-				
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,								
_	• 1		Measure Sub Total:				Sub Total:		
	Field Notes:	A CONTRACTOR							
		Work Order Grand Total: Grand Total:							

Client ID: 80008KN0761 Alt. Client ID: KNOX Work Order Name: WO/80008KN0761/1 Report Run On: 5/8/2010

Version 8.6.0 Page 13 of 13